



HOB - PARROT GTM3 USER INTERFACE REBOOT

DESCRIPTION:

User Interface reboot when using Assisted function - Fish/Seafood - **SousVide Salmon**

- **Issue happens ONLY if polish languages is selected and Assist SousVide Salmon is used**
- Root cause: issue in polish translation "50°C reached: Place the bags in the water and start timer when ready"



SPARE PART:

All Parrot GTM3 configured User Interface.

QES CODE:

During the intervention please use the following QES Code:

| | |
|-----------|-------|
| Component | 617 |
| Defect | 31 SW |

Solution:

Exchange the User Interface with new spares

REVISION:

| Revision | Date | Description | Author | Approved by - on |
|----------|---------|-------------------|--------|------------------|
| 00 | 02/2020 | Document Creation | BSP | |