




### OVEN – FOOD PROBE SOCKET ON OVC5000 POB

**DESCRIPTION:**

Mechanical Coding of Food Probe socket on OVC5000 has changed from 3-teeth to 2-teeth.

**Solution:**

To fit into the 2-teeth housing please cut the **disturbing teeth** by a **cutter**.

**QES CODE:**

Use the following QES Code during the investigation

Component	615
Defect	xx

**REVISION:**

Revision	Date	Description	Author	Approved by - on
00	08/2020	Document Creation	BSP	Ernst Waldmannstetter