



Vibration noise in 1780 static combi bottom and cabinets

DESCRIPTION:

The noise comes from tubes vibrating against the back of the appliance.



SOLUTION:

Carefully bend the tube away from the back of the appliance.



Use the following QES Codes when reporting the Service Order:

Component	101 Casing/Cabinet with parts
Defect	09 Noise

MODELS INVOLVED:

PNC	From serial number	To serial number
925503xxx	Week 020	Week 051
923583xxx	Week 020	Week 051

REVISION:

Revision	Date	Description	Author	Approved by - on
00	01/2021	Document Creation	Anna Grimlund	Stefania Piccin