






Spare part replacement information

140055195063 Turbidity Conductivity sensor part number replacement

DESCRIPTION:

140055195063 Turbidity Conductivity sensor part number replace with 140055195089.

CHANGING DETAIL:

Before	After
<p>Part number : 140055195063</p> <div style="display: flex; justify-content: space-around;">  <div style="text-align: center;"> <p>1.Current PCB layout</p>  </div> </div>	<p>Part number : 140055195089</p> <div style="display: flex; justify-content: space-around;">  <div style="text-align: center;"> <p>1.Modify PCB layout</p>  </div> </div> <p>2.changing capacitor.</p>  <p>C10, C11 : 4nF --> 3.3nF</p>

SPARE PART NUMBER:

Current spare part No.	Description	New spare part No.	Description
140055195063	TURBIDITY CONDUCTIVITY SENSOR	140055195089	TURBIDITY CONDUCTIVITY SENSOR

ADDITION SOLUTION:

Spare part replacement.

Revision	Date	Description	Author	Approved by - on
00	08/04/2021	Document Creation	Vatcharapong	-