

SERVICE BULLETIN DISHWASHERS

FAULTY DUCT

DESCRIPTION:


There is a possibility of an issue being present in an appliance, where duct won't be kept in the correct place on upper basket.

Serial number range of the possible affected products: 106XXXXX – 115XXXXX


SOLUTION:

Replacement of the duct with the one from the TDS database.

Examples of KO (improperly holding onto the basket) component and OK component below:



1. Hooks are improperly hooked to the basket



2. Properly mounted component

SPARE PART NUMBER:

Spare part number according to the TDS.

Old spare part code	New spare part code	Description	
-	-	-	

It's possible to insert the column to the position when using exploded views. **QES CODE:**

During the intervention please use work code 17 and be sure to place it in Goodwill, with following component code and defect code:

Component	518
Defect	08

Q&CI – MP

MODELS INVOLVED:

Dishwasher of width 45cm.

Serial number range of the possible affected products: 106XXXXX – 115XXXXX

INTERCHANGEABLIITY:

N/A

REVISION:

Revision	Date	Description	Author	Approved by - on
00	04/2021	Document Creation	Sebastian Dziura	