



### ICE FORMATION IN COMBI TOP FREEZER COMPARTMENT

#### DESCRIPTION:

Ice formation in the middle of the freezer compartment of combi top appliances.



#### SOLUTION:

Replace the freezer door according to the spare part list below.

Before replacing the door, make sure that the new spare part door has the new design with a straight door channel (image 1)

#### Image 1



**Image 2**

Old design, replace this type of door.



**QES CODE**

Component	154
Defect	80

**MODELS INVOLVED AND SPARE PART NUMBER**

This problem occurs in all appliances in the list below from start of production to week 31/2021

PNC	Spare part number	PNC	Spare part number
92599222400	4055516845	92599224400	4055516522
92599222500	4055516928	92599224500	4055516522
92599222600	4055516928	92599224600	4055516522
92599222700	4055516845	92599225500	4055516522
92599222800	4055516928	92599225600	4055516522
92599222900	4055516845	92599225700	4055516522
92599223000	4055516928	92599225900	4055516928
92599223100	4055516522	92599226000	4055516928
92599223200	4055516787	92599226100	4055516522
92599223300	4055516522	92599226200	4055516522
92599223400	4055516787	92599226600	4055516928
92599223500	4055516522	92599226700	4055516928
92599223600	4055516845	92599226800	4055516928
92599223700	4055516928	92599227000	4055516928

92599223900	4055516928	92599227100	4055516522
92599224000	4055516928	92599228200	4055516928
92599224100	4055516845	92599228400	4055516522
92599224200	4055516928	92599228500	4055516522
92599224300	4055516522		

**REVISION:**

<b>Revision</b>	<b>Date</b>	<b>Description</b>	<b>Author</b>	<b>Approved by - on</b>
00	08/2021	Document Creation	Anna Grimlund	08/21 Yurii Ravskyi
01	10/2021	Added description and images.	Anna Grimlund	Yurii Ravskyi
02	11/2021	New images	Anna Grimlund	Yurii Ravskyi