



**NOTE:** In the event of removing the turntable motor cover this part should be refitted using screw connection: 50280577003 (7-15)