



NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection: **5028 05 76-00/5 (71)**