



NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection: **50280576005** (7-1)