



NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection: **50280576005 (7-1)**