



NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection: LX-CZA001WRE0 (7-15)