



		1A	2A	3A	4A	5A	6A	7A	8A	9A	10A	11A	12A	Male tabs qty.		
		2	2	2	2	2	2	2	2	2	2	2	2	Marking		
		CONTACTS (REAR VIEW)														
		1	2	3	4	5	6	7	8	9	10	11	12	Marking		
		2	2	2	2	2	2	2	2	2	2	2	2	Male tabs qty.		
POSITIONS		0	1	2	3	4	5	6	7	8	9	10	11	12	Marking	
			X	X							X	X	X		0°	OFF
			X		X	X	X	X		X	X	X			40°	Lamp
			X							X					80°	ECO
			X	X	X	X		X	X	X	X				120°	Strip (T+B+F)
			X	X	X		X	X	X	X					160°	Turbo grill (G+T+F)
			X	X		X		X	X	X					200°	Bottom
			X	X	X	X		X	X	X					240°	Pizza (G+B+F)
			X	X	X			X	X	X					280°	Defrost (F)
			X	X		X	X	X	X						320°	Static (T+B)