


SUPPLY POWER CORD



**SWITCHING DIAGRAM**

POSITIONS	P1	P2	P3	P4	P5	P6	P7	P8	P9	FUNCTIONS
0		X						X		0° ∠
1						X	X	X		36.00° ∠
2	X		X			X	X	X		72.00° ∠
3	X			X		X	X	X		108.00° ∠
4		X				X	X	X		144.00° ∠
5					X	X	X	X		180.00° ∠
6			X	X		X	X	X		216.00° ∠
7	X		X	X		X	X	X		252.00° ∠
8	X	X		X		X	X	X		288.00° ∠
9	X	X			X	X	X	X		324.00° ∠