

ELECTROLUX SIEGEN GmbH, In der Steinwiese 16, D-57074 Siegen


Gas-connection

For the Scandinavian countries (Finland, Norway, Sweden) and Dänemark.

From 95.09.01 on, some caravan refrigerators for the above countries get new gas-connections.

The gas-connections are exchangeable with the old version.

New gas-connection cpl.



spare part no.: 295 2244-00/8 L = 142, different holder
 295 2244-10/7 L = 92
 295 2244-20/6 L = 342
 295 2244-30/5 L = 142, different holder

spare part no.: 295 2249-00/7 L = 80
 295 2353-00/7 L = 363

Spare parts numbers for new gas-connection cpl.	Model
295 2244-00/8	RM 4200, RM 4201, RM 4210, RM 4211, RM 4230, RM 4231, RM 4260, RM 4261 and GM 65H
295 2244-10/7	RM 4215, RM 4235, RM 4265, RM 4285, RM 4365, RM 4405, RM 5215, RM 5275 and RM 5405
295 2244-20/6	RM 4203 and GM 60B
295 2244-30/5	RM 4180 and RM 4181
295 2249-00/7	RM 4212, RM 4213, RM 4233, RM 4263, RM 4240, RM 4270, RM 4271, RM 4280, RM 4281, RM 4300, RM 4301, RM 4360, RM 4361, RM 4370, RM 4371, RM 4400, RM 4401, RM 5211, RM 5270, RM 5271, RM 5400, RM 5401 and GM 90H
295 2353-00/7	RA 4420, RA 4421, G 105, GE 105 and NK 105