



REINFORCED HEATERS WITH THERMAL FUSES

In case of repeated faults of the heater, caused by corrosive agents dissolved in water, the heaters with thermal fuses featured in the functionality **ENV06** (EWM1100-2100-2500-3500), reinforced and protected against the corrosion of: detergent, chlorine, limestone etc, are available as spare parts.

SPARE PARTS



To identify the heater, check the part no. printed on the flange indicated by the arrow (see figure).



EN	Publication no.	599 71 83-40	Rev. 00	04/2009	dmm

599 71 83 40