


## SERVICE BULLETIN

### WINE CELLARS 3140


#### Thermostat, 295 52 45-01

This thermostat is no longer produced and thus, no longer available.  
There is no replacement thermostat.

Note that it is necessary to replace the whole existing "Control panel, cpl"  
since the new thermostat is not compatible with the old thermistor.



Thermostat



Control panel, cpl  
*General view. Features may vary.*

Different wine cellar models are equipped with different control panels. To know which replacement part to get, please follow these steps:

1. Enter the PNC of the wine cellar in TDS/ProCorner.
2. Locate the part number of the existing "Control panel, cpl".
3. Enter this part number in TDS/ProCorner and replacement information will be shown.