

INSTRUCTIONS REGARDING GLASS CERAMIC INSTALLATION CLAMPS

Re: All glass ceramic cooking surfaces from the "Promise" range without frames in flush-fitted installation (with the exception of GK56P 0)

Reason: The cut-out in the work surface does not correspond to the planning documents. With a joint width which is unequal all round (e.g. left 12mm, right 14mm), the device cannot be centred properly, because it is lodged in the cut-out in the work surface by the Opti-Fix clamps. Under these conditions an unequal joint width is incurred all round.

Possible action:

Press the Opti Fix installation clamps gently together with a pair of pliers in order to reduce the tension force. The clamps can be approached from one or several sides in this situation. If the desired effect is not attained, repeat the procedure with somewhat more force being applied.

