



**TOP COUNTERWEIGHT MODIFICATION**

**DESCRIPTION:**

For Prometeo washing machines double screwed counterweight has been replaced by triple screwed. Modification is not interchangeable and the old part is not longer available.

| Double screwed top counterweight   | Triple screwed top counterweight  |
|--|---|
|  |  |
| 147189901/1  | 147189910/2   |

**SOLUTION:**

In case of exchange, double screwed top counterweight has to be replaced by triple screwed. The new counterweight requires different front and back shell assemblies. To order correct parts please refer to below table.

**SPARE PARTS:**

| Part Detail                         | From              |          | To                |          |
|-------------------------------------|-------------------|----------|-------------------|----------|
|                                     | Spare part number | Quantity | Spare part number | Quantity |
| Top counterweight                   | 147 18 99-01/1    | 1        | 147 18 99-10/2    | 1        |
| Front tub shell                     | 132 73 64-20/2    | 1        | 132 73 64-30/1    | 1        |
| Back tub shell assy (1000~1200 rpm) | 147 76 10-11/5    | 1        | 147 76 10-50/3    | 1        |
| Back tub shell assy (850 rpm)       | 405 50 85-71/8    | 1        | 147 76 10-60/2    | 1        |
| Top counterweight screws            | 132 72 91-00/9    | 2        | 132 72 91-00/9    | 3        |

**MODELS INVOLVED:**

| PNC       | Model name | Region |
|-----------|------------|--------|
| 914900237 | EWf85661   | AP     |
| 914900238 | EWf85761   | AP     |
| 914900239 | EWf10741   | AP     |
| 914900240 | EWf10751   | AP     |
| 914900241 | SWf85661   | AP     |
| 914900242 | SWf10761   | AP     |
| 914900243 | EWf85661   | AP     |
| 914900244 | EWf85761   | AP     |
| 914900245 | EWf10741   | AP     |
| 914900246 | EWf10751   | AP     |
| 914900247 | EWf85661   | AP     |
| 914900248 | EWf85661   | AP     |
| 914900249 | EWf85761   | AP     |
| 914900250 | EWf85761   | AP     |
| 914900251 | EWf10741   | AP     |
| 914900252 | EWf10741   | AP     |
| 914900253 | EWf10751   | AP     |
| 914900257 | EWf10751   | AP     |
| 914900268 | EWf85651   | AP     |
| 914900269 | EWf10641   | AP     |
| 914579848 | ZWH5120P   | EU     |
| 914579845 | ZWH7120P   | EU     |
| 914579846 | FWH7120P   | EU     |
| 914579851 | ZWH6120P   | EU     |
| 914579849 | ZWH6100P   | EU     |
| 914579850 | FWH6100P   | EU     |

| PNC       | Model name | Region |
|-----------|------------|--------|
| 914579852 | FWH6120P   | EU     |
| 914579847 | ZWH5100P   | EU     |
| 914579854 | ZWH6120P   | EU     |
| 914579859 | PWH71062   | EU     |
| 914900274 | EWf10741   | EU     |
| 914900277 | ZWH5855P   | EU     |
| 914900278 | ZWH5105P   | EU     |
| 914900279 | ZWH7120P   | EU     |
| 914579896 | ZWH7120P   | EU     |
| 914579870 | FWH6125P   | EU     |
| 914579868 | ZWH6121P   | EU     |
| 914579869 | ZWH6101P   | EU     |
| 914579897 | FWH6122P   | EU     |
| 914900270 | EWf80561   | AP     |
| 914900271 | EWP8555    | AP     |
| 914900272 | EWP1054S   | AP     |
| 914579835 | ZWG2100P   | EU     |
| 914579836 | ZWG2120P   | EU     |
| 914579837 | ZWG2120P   | EU     |
| 914579838 | ZWG1100P   | EU     |
| 914579839 | ZWG1100P   | EU     |
| 914579840 | ZWG1120P   | EU     |
| 914579841 | ZWG1120P   | EU     |
| 914579842 | FWG1125P   | EU     |
| 914579843 | ZWG1121P   | EU     |
| 914579844 | FWG1121P   | EU     |

**REVISIONS:**

| Revision | Date    | Description       | Author | Approved by - on |
|----------|---------|-------------------|--------|------------------|
| 00       | 02/2011 | Document Creation | RR     | TK – 08/2011     |