

SERVICE BULLETIN DISH CARE

New spare part solution for control panels and panel buttons

Due to changes in logistic setup it will no longer be possible for Electrolux to provide panel buttons as spare parts for freestanding and built under dishwashers with plastic panels. Fully integrated built-in appliances are excluded from the contents of this service bulletin.

As a consequence any case of damage to any of the buttons will result with replacement of the whole control panel assembly. This change has been implemented and is valid for control panels produced from January 2014.



1. Example of panel influenced by this change

EXEMPTIONS

At the moment there are no exemptions defined to this rule.

REVISION:

Revision	Date	Description	Author	Approved by - on
01	05/2014	Pricing Direction	Rickard Nilsson	
02	12/2014	Pricing Direction – removed	Marcin Kobiałka	

EN SDT – MK 1/1 599 77 78-48 Rev.02