

Control Unit/Switch unit – change of part codes

GENERAL The part code of the Switch Unit and the Control Unit used in the above models has changed.

Note: The function of the new control unit has changed in the 'clock set mode' to meet with recently introduced European Regulations. This change will now switch the display back light off after three minutes when the microwave oven is not in use. The clock display is still present and the back light will switch on once the microwave oven is used again.

Important: Both old parts must be replaced as a pair.

IMPLEMENTATION DATE: 2010-02-18 (1-TB-M1002059, 2-TB-M1002060, 3-TB-M1002061, 4-TB-M1002062)

PNCs:

- 1.) 947608509, 947608511, 947608519
- 2.) 947608284, 947608285, 947608514
- 3.) 947608517, 947608518, 947608523, 947608524, 947608525, 947608526
- 4.) 947608169

Interchangeability:



Parts:

SB No	Ref. No	DESCRIPTION	OLD PART No.	Q' ty	NEW PART No.	Q' ty	Replacement Kit Part No	Interchangeability
1	3-1	Switch Unit	FPWBFA077URK1 (50286986000)	1	FPWBFA115URK0 (4055082236)	1	4055082301	C
	3-2	Control Unit	FPWBFA101URK1 (4055058947)	1	FPWBFA112URK0 (4055082228)	1		C
2	3-1	Switch Unit	FPWBFA079URK1 (50286405001)	1	FPWBFA116URK0 (4055082418)	1	4055297743	C
	3-2	Control Unit	FPWBFA101URK1 (4055058947)	1	FPWBFA112URK0 (4055082228)	1		C
3	3-1	Switch Unit	FPWBFA075URK1 (50286391003)	1	FPWBFA113URK0 (4055082392)	1	4055297750	C
	3-2	Control Unit	FPWBFA101URK1 (4055058947)	1	FPWBFA112URK0 (4055082228)	1		C
4	3-1	Switch Unit	FPWBFA078URK1 (50287733005)	1	FPWBFA114URK0 (4055082400)	1	4055297768	C
	3-2	Control Unit	FPWBFA101URK1 (4055058947)	1	FPWBFA112URK0 (4055082228)	1		C

Note 2014-02-26

Part 4055082228 has been replaced by 40550112082 (TB-M1402129).

Parts are fully interchangeable.

Revision	Date	Description	Author	Approved by - on
00	06/2014	Document Creation	BLANKA KUCHARSKA ROB GRIFFITHS	B.K. 2014-06