

Dometic GmbH In der Steinwiese 16 D-57074 Siegen www.dometic.com

RMD 8501/8505/8551/8555, RMDM 8501/05/51/55, RMDT 8501/8505/8551/8555

Ice formation in the freezer compartment

In above mentioned fridges between serial number 334xxxxx and 451xxxxx it can come to increased ice formation in the freezer compartment.

The new door gasket, spare part number 289 0584-10/1 will solve this problem.



Example ice formation in the freezer compartment

