

SERVICE BULLETIN REFRIGERATION BUILT IN

Flex II Compressor control issue

DESCRIPTION:

The appliance can be noisy/vibrating when the compressor is running. The root cause can be the Flex drive II, the plastic case creates a rattling noise (the component is not glued inside board).

SOLUTION:

Replace the Flex II compressor drive board.



SPARE PART NUMBER:

Old spare part code	New spare part code	Description	From
140025578273	140025578315	Card,control,Compressor,FLEX II	Start of production to week 43/18
140025578307	140025578323	Card,control,Compressor,FLEX II	Start of production to week 43/18

QES CODE:

Use the following QES Codes when reporting the Service Order:

Component	629
Defect	22

MODELS INVOLVED:

	PNC	Serial number involved	Spare part to use
	922738003	from start of prod. to week 43/18	140025578315
	922738004	from start of prod. to week 43/18	140025578315
	922738008	from start of prod. to week 43/18	140025578315
	922738009	from start of prod. to week 43/18	140025578315
	922782002	from start of prod. to week 43/18	140025578315
	922782007	from start of prod. to week 43/18	140025578315
	922782009	from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
		from start of prod. to week 43/18	140025578315
FN	0&CI – AG	2/3	599 82 66-48 Rev 00
			244 A / DD=48 RAV III

EN Q&CI – AG 2/3 599 82 66-48 Rev.00

923583031	from start of prod. to week 43/18	140025578315
923585012	from start of prod. to week 43/18	140025578315
925504025	from start of prod. to week 43/18	140025578315
925511024	from start of prod. to week 43/18	140025578315
925511030	from start of prod. to week 43/18	140025578315
925511031	from start of prod. to week 43/18	140025578315
925514015	from start of prod. to week 43/18	140025578315
925514017	from start of prod. to week 43/18	140025578315
925514019	from start of prod. to week 43/18	140025578315
925516020	from start of prod. to week 43/18	140025578315
925516055	from start of prod. to week 43/18	140025578315
925516064	from start of prod. to week 43/18	140025578315
925516075	from start of prod. to week 43/18	140025578315
925582007	from start of prod. to week 43/18	140025578323
925582027	from start of prod. to week 43/18	140025578323
925582036	from start of prod. to week 43/18	140025578323

REVISION:

Revision	Date	Description	Author	Approved by - on
00	01/2019	Document Creation	Anna Grimlund	Stefania Piccin