


STARTING DEVICE – NEW TERMINAL BLOCK

DESCRIPTION:

New starting device /motor protection for appliances with compressor MH1050Y. The terminal block SX.J7 replaces starting devices SX1J7 and SS1J7.


SOLUTION:

New terminal block SX.J7



Starting device SS1J7

Move the white connector block on the starting device SS1J7 to the new terminal block.



Old spare part	New spare part	Description	From
2425640733		Starting device, motor protector, SX1J7	
2425640717		Starting device, motor protector, SS1J7	05/2016
	140013370691	Terminal block, motor protection, SX.J7	01/2018

The MH1050Y compressor replacement kits (140014520278, 140014520534) have been updated with the new terminal block.

QES code:

Component: 304 starting device

Defect: 22 electrical defect

MODELS CONCERNED:

PNC	PNC	PNC	PNC	PNC	PNC
923000495	925052287	925070421	933012470	933015152	933024068
923581001	925052288	925070422	933012478	933015153	933024070
923581024	925052289	925070602	933012480	933015156	933024071
923581032	925052357	925070603	933014062	933015158	933024072
923581035	925052358	925070604	933014063	933015164	933024073
923581037	925052359	925070605	933014067	933017053	933024074
923581051	925052360	925070606	933014076	933017055	933024075
923584002	925052361	925070607	933014078	933017057	933024077
923584021	925052362	925070608	933014079	933024022	933024080
923584030	925052366	925070609	933014085	933024023	923581009
923584032	925052367	927024260	933014086	933024030	923581018
923584033	925052368	927024340	933014093	933024031	923581019
923584034	925052369	927024345	933014094	933024032	923581020
923584037	925052370	927090460	933014095	933024033	923581025
923584040	925052373	927090580	933014099	933024034	923582000
923584048	925052374	927090581	933014100	933024038	923582001
923586003	925052387	927090840	933014103	933024039	923582003
923586008	925052388	927090845	933014104	933024041	923582004
923586010	925052391	927091040	933014105	933024042	923582006
923586016	925052392	927140251	933014107	933024044	923584013
923586017	925070403	927140260	933014108	933024045	923584019
923586018	925070404	927140265	933014109	933024046	923584026
923586019	925070405	927140351	933014111	933024047	923584027
923775019	925070406	927140380	933015107	933024048	923586000
923775020	925070407	927140560	933015108	933024050	923586002
923775022	925070408	927141020	933015119	933024051	923586004
923794000	925070409	927141031	933015126	933024052	923586012
923794005	925070410	933002980	933015129	933024053	923586014
923794007	925070411	933002981	933015135	933024054	923586015
923794010	925070412	933002982	933015139	933024055	923794004
923794011	925070413	933009214	933015142	933024056	923794009
923794012	925070414	933009217	933015143	933024057	
925052274	925070415	933012448	933015144	933024058	
925052275	925070416	933012457	933015146	933024060	
925052285	925070417	933012461	933015147	933024062	
925052286	925070418	933012466	933015151	933024067	

REVISION:

Revision	Date	Description	Author	Approved by
0	04/2019	Document creation	Anna Grimlund	Stefania Piccin