



HOOD SPLIT MODEL - SELF ACTIVATION

DESCRIPTION:

Cooker Hood is switching itself on/off or change the speed without receiving a relevant command from end-consumer.

REASON:

Humidity inside the control. Steam enter into the space between glass and steel, after the condensation the water arrives to the control pcb.

PRODUCTS AFFECTED:

All hoods belonged to the PNCs listed in below table produced before week 21/2019 (before SN 921*****)

PNC	Model denomination	Template Model	Brand	Factory ID
942051026	BHC54751BA	Split	Best	ITB
942051027	BHC54750WA	Split	Best	ITB
942051024	BHC84751BA	Split	Best	ITB
942051025	BHC84751WA	Split	Best	ITB
942051177	BEPOM55VN	Split	Unbranded (Fournier)	ITB
942051178	BEPOM55VB	Split	Unbranded (Fournier)	ITB
942051175	BEPOM80VN	Split	Unbranded (Fournier)	ITB
942051176	BEPOM80VB	Split	Unbranded (Fournier)	ITB
07F62050	/	Split	Best	ITB
07F62051	/	Split	Best	ITB
07F62052	/	Split	Best	ITB
07F62053	/	Split	Best	ITB
07F62056	/	Split	Unbranded (Fournier)	ITB
07F62057	/	Split	Unbranded (Fournier)	ITB
07F62054	/	Split	Unbranded (Fournier)	ITB
07F62055	/	Split	Unbranded (Fournier)	ITB

SOLUTION:

When the hood is affected by self-activation, the service technician must replace the inferior glass assembly (glass + control) instead of only control board.



SPARE PART NUMBER:

PNC	Spare part code	Part description
942051026	88466438	Inferior glass assembly, control board + glass
942051027	88466446	Inferior glass assembly, control board + glass
942051024	88466479	Inferior glass assembly, control board + glass
942051025	88466495	Inferior glass assembly, control board + glass
942051177	88466453	Inferior glass assembly, control board + glass
942051178	88466461	Inferior glass assembly, control board + glass
942051175	88466487	Inferior glass assembly, control board + glass
942051176	88466503	Inferior glass assembly, control board + glass
07F62050	88466438	Inferior glass assembly, control board + glass
07F62051	88466446	Inferior glass assembly, control board + glass
07F62052	88466479	Inferior glass assembly, control board + glass
07F62053	88466495	Inferior glass assembly, control board + glass
07F62056	88466453	Inferior glass assembly, control board + glass
07F62057	88466461	Inferior glass assembly, control board + glass
07F62054	88466481	Inferior glass assembly, control board + glass
07F62055	88466503	Inferior glass assembly, control board + glass

REVISION:

Revision	Date	Description	Author	Approved by - on
00	16.09.2019	Document Creation	Claudia Terzoni	Ermes Sampaolesi