

Technical Bulletin Nº CB1063

Issue: 1 Date: 5/20

Induction Cooktop Clearances

AEG

Follow the manufactures recommended clearances, (these can be found in the owner manual) if not stated the following can apply to the Models/PNC's linked to this bulletin.

No bench top/cabinet ventilation gap required.

An **8mm** minimum clearance from the top of an oven and the underside of the cooktop is required.



