



P09473023815

NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection : **50282957005**(7-10)