



Electrolux

SERVICE BULLETIN

REFRIGERATION


3110

Caravanrefrigerator

Reg. Nr. 438/96

ELECTROLUX SIEGEN GmbH, In der Steinwiese 16, D-57074 Siegen

Caravanrefrigerator



The Factory is aware of claims where the furniture was scratched when dismantling the refrigerator.

During installation of the refrigerator by the vehicle manufacturer (OEM) a sharp edge is formed at the point where the fixation screw is protruding.

This sharp edge damages the furniture when the refrigerator is moved out.

In order to avoid this scatching of the furniture it is **absolutely necessary** to move in four sheet metal pieces, e. g. spatulas, between the refrigerator side walls and the adjacent furniture walls, as shown in above sketch.