

## PRESENCE OF OIL ON THE HOSES OF THE COMPRESSOR

### DESCRIPTION:

In some appliances some oil has been used to protect the welding of the compressor hoses.

The presence of oil is not due to a gas leakage.

The affected appliances are marked with a label (fig. 1) placed on the capacitor.




Fig. 1