



iTex UI - Popup messages to be confirmed



DESCRIPTION

Oven with iTex UI displays popup message and chances of customer not able to interpret correctly

Reason

Old software has different description compared to new software

Example

iTex 10 - Old software	iTex - New software
	

TROUBLESHOOTING

All popup messages on the display on iTex UI should be confirmed clicking the rotary

AFFECVTED UI's

iTex UI from Serial No. 705xxxxx and Rotary seat center control panel

REVISION

Revision	Date	Description	Author	Approved by - on
00	01/2018	Document Creation	BSP	Josef Leis - 11/01/2018